

State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

Supervisor DR

Inspection Report Minerals Regulatory Program

Report Date: May 16, 2005

Mine Name: East Veyo Cinder Knoll Operator or Permittee Name: Sunroc Corporation Permittee Mailing Address: 180 North 300 East St. George, Utah 84770		number: S/ion Date: A	053/067 pril 25, 2005	
Inspector(s): Doug Jensen	Weather: Cool, Windy, Heavy Rain Inspection Start Time: 5:30 PM Inspection End Time: 6:00 PM Site location/Area Inspected (i.e. Pit #):			
Other Participants: None	Site loc	ation/Area I	nspected (i.e.	Pit #):
Permit Status: Active	Surface Ownership: BLM			
Current Acreages:	Mineral Ownership: BLM			
Total Permitted (Bonded): Total Disturbed: ~2 acres	Mineral Mined: Cinders Type of Mine: Open Pit			
Total Disturbed: ~2 acres	Type of	Wille: Oper	1 PIL	
Elements of Inspection	Evaluated	N/A	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds				
2. Public Safety (open shafts, adits, trash,				
signs, highwalls)				
3. Protection of Drainages4. Explosives, magazines			H	H
5. Deleterious Material	H		H	H
6. Roads (maintenance, surfacing, dust control,				
safety)				
7. Concurrent Reclamation				
8. Erosion Control		\boxtimes		
9. Demolition		\bowtie		
10. Backfilling and Grading (trenches, pits, roads, highwalls, shafts, drill holes)				
11. Water Impoundments				
12. Soils	Ħ	Ħ	П	
13. Revegetation		\boxtimes		
14. Air Quality		\boxtimes		
15. Facilities				
16. Other				



Inspection Date: April 25, 2005; Report Date: May 16, 2005

Page 2 of 2 S/053/067

Purpose of Inspection:

Visited the site to GPS the disturbed area to confirm acreage at the site.

Inspection Summary:

Started to GPS the site when it began to rain. It rained hard enough that I didn't complete the survey. Waited at the site for the rain to quit. When it didn't let up I left the site. Will GPS the site at another time.

The disturbance at the site is presently <2 acres. This footprint hasn't changed for some time, the operation is presently developing a highwall and a small pit in which they have been working for the last year or so. The permitted area is fenced and signs mark the entrance to the site.

Directions to the site:

Refer to previous inspection memos.

GPS data:

None gathered.

Inspector's Signature

Date: May 16, 2005

DJ:jb

cc: Rody Cox, BLM, St George FO

O:\M053-Washington\S0530067-EastVeyoCinderKnoll\inspections\04252005insp.doc